

These articles and information is brought to you by The 1937 and 1938 Buicks Club. For more information please contact us at:

http://autos.groups.yahoo.com/group/1937and1938Buicks/ or WWW.1937and1938Buicks.com

#### -- Warning Notice --

It the mission and goal of 1937 and 1938 Buicks Club is to provide information, helpful hints, advice, directions and reference information for the repair, maintenance, authentic restoration and knowledge development in regards to 1937 and 1938 Buick's. Content is offered as informational only.


The 1937 and 1938 Buicks Club does not knowingly accept false or misleading content or advertising. Nor does The 1937 and 1938 Buicks Club assume any responsibility for the consequences that may occur should any such material appear.

The 1937 and 1938 Buicks Club does not guarantee the quality of any information which is included in this or any other publication. Under no circumstances shall The 1937 and 1938 Buicks Club be liable for any damages, losses, or injuries resulting from use reliance on the content of this or any other publication. Any reliance on this or any other publication content is at your own risk.

As a precautionary measure, The 1937 and 1938 Buicks Club strongly recommends that you contact a professional mechanic or restoration shop to check your work or answer specific questions.

#### -- Copyright Notice --

All rights reserved. All documents and publications on The 1937 and 1938 Buicks Club web site or that can be down loaded from The 1937 and 1938 Buicks Club web site are protected under both U.S. Federal copyright law and international treaties. No component of this site, including text, images and computer code, may not be reproduced or copied in any form or by any means--electronic, graphic, digital or mechanical, including photocopying or information storage & retrieval systems--without the express prior written permission of The 1937 and 1938 Buicks Club.



VOLUME XVIII . NUMBER 6 . JULY/AUGUST 2000



# BY HARRY LOGAN (#651) EDITOR

Dear members. We set an all-time membership record of 642 paying members as of August 31, the end of our 1999-2000 publishing year. We have been growing larger every year. Pretty good for a club with such a narrow focus. Thanks for your help in recruiting new members.

This street scene show a 1937 Buick two door sedan without a front bumper and a damaged running board. Ahead of the Buick may be another '37 or '38 Buick Behind it is a Packard convertible sedan. The theater is playing the 1945 movie Love Letters starring Jennifer Jones and Joseph Cotton. Duffy's Tavern, another 1945 movie is also advertised. The Buick made it through the war but is showing signs of wear and tear. Thanks to Mark Garcia (#1390) for sharing this photo.

I received this e-mail from the Ukrainian

Republic, formerly part of the Soviet Union. The sender has a Flint built 1938 Buick Special and is requesting help. Can anyone help him? His email address is: wlld@magen.mk.ua Thanks.

"I am by the owner of the automobile; Buick -Special, issued in 1938 by firm; General Motors, (number of the engine 43494885, number the chassis 13303327)."

"I want to inform you, that this automobile was present Soviet Command (personally Marshal Gukov) during Great Patriotic War, when the Soviet Army and the armies of the allies have met on Elba. After war of the Bugs was nominated command by the Odessa Military District, And this automobile it (he) has presented the chief of a staff, which lived at one to Odessa, where I also have bought the automobile. On this fact I addressed in a Museum of the Armed Forces USSR in





Moscow, where this fact was confirmed, but, unfortunately, data on this machine at them is not present. On this I ask you whenever possible to confirm this fact for comparison and establishment of authenticity of this automobile. During many years I used this large and convenient machine. But in due course its (her) engine has left out of operation (the piston group has come in unsuitability) and to restore it (him) to me it was not possible."

"I the pensioner, participant of Great Patriotic War,

invalid II of group, am addressed (paid) to you with the request. As this automobile is historical value (automobile 62 years) I ask to help me to restore it (him)."

This photo from the Washington DC Post Magazine shows actress Hattie McDaniel visiting Howard University in 1940. She had become the first African American to win an Academy Award for her supporting role as Mammy in "Gone

With The Wind." From what I can see, it looks like she was brought to Howard University in a 1938 Buick. Thanks to **Charles Jekofsky** (#524) in Washington, DC for sharing this photo.

This brown 37 slant back sedan model 47, at the top of page 3, belongs to Ray Shanahan in San Rafael, CA in the San Francisco Bay area. Ray is also restoring a '41 Buick.

These two photos of Molly Fisher were taken in Flint, Michigan in front of her father's nearly new

1937 Special 2-door slant-back sedan Model 44. Molly's father had a neighbor, an executive at GM, who got a new car each year. So, in '38, as the story goes, her dad bought from him the car you see in these two photos. Molly now lives in sunny Hawaii. She saw our Club web page on the Internet and sent me these photos and story. Thanks Molly.

Club members Dan and Marian McLaughlin (#466)



### **TORQUE TUBE**

You can now find your '37-'38 Buick Club on the World Wide Web:

http://www.classicar.com/clubs/buick/buick.htm

The TORQUE TUBE is published every two months for the enjoyment of the 1937-1938 Buick Club. Membership dues are \$34.00 per year US, \$35.00 per year Canada or Mexico and \$40.00 per year for all others. All issues mailed First Class and Overseas issues are mailed Air Mail-Printed Matter unless Surface Mail, at \$35.00 per year, is requested. All memberships run September 1 to August 31 of the following year. Persons joining during the year will receive all back issues from September 1. All payments must be in U.S. funds. Please make your check payable to the 1937-1938 Buick Club.

Please send all articles, ads subscriptions and inquires, etc. to:

The TORQUE TUBE 1005 RILMA LANE LOS ALTOS, CA 94022 USA You can reach Harry Logan by PHONE/FAX (650) 941-4587 or by E-mail: harrylogan@earthlink.net

Printer Liaison: Bill Olson, #427
Printer: Conrads Printing, Lancaster, Ohio

All rights reserved. No part of this newsletter may be reproduced in any form without written permission from THE TORQUE TUBE

attended the 37/38 Buick Meet in Minnesota in June in their black 1937 Special Coupe.

Then they continued on to three other car meets, one after the other! They next went to the Buick Driving Enthusiasts Meet at Deadwood, South Dakota, then to the AACA Regional

Spring Meet at Grand Forks, North Dakota, and to end things, the AACA Central Division's tour of the

North Dakota Badlands. June

was a very busy month for them and their 37-46, shown below, which performed flawlessly.

They encountered this male Bison along the road in

Theodore Roosevelt National Park in North Dakota. They took the photo from inside their car as these bulls can be testy. (top of page 4).

**John Jackson** (#1107) in Illinois reports he had resigned himself to thinking his '38 grill would be dull forever. Then he heard a tip about using steel wool and them immediately waxing the grill. It worked very well and his '38 grille now actually shines!



I've just returned from an interesting WWII history tour of Germany and the Netherlands with 30 others. In Berlin, our group toured the huge Luftwaffe Ministry building, the site on which Adolf Hitler's Reichchancellery once stood, the rebuilt Reichstag, an enormous WWII

air raid bunker and the 1936 Olympic Stadium.

This child's sandbox I'm standing next to was where Hitler's body was burned after he committed suicide in April, 1945. It's where the entrance to his bunker behind the Reich's Chancellory used to be.

What was left of the bunker and

Chancellory have been removed and replaced by a large apartment complex with a courtyard and children'splayground in the center. I doubt if any of the children or their parents know the history of what happened here 55 years ago.

We visited two concentration camps, the once top secret rocket re-

search and launching facility at Peenemunde on



the Baltic Sea and went aboard the submarine U-995 in Kiel. In the Netherlands we visited two war museums and saw the infamous "Bridge Too Far" at Arnhem.

Then I spent five days in Belgium visiting friends I made when I lived there in the 1960's. My Ameri-

can friend John Largent married Daniella, a Belgian lady I introduced him to. (see photo). It was a pleasure to spend a couple of days with them.

neapolis, MN on 8/3/37,' this car was written by the Minneapolis Zone itself, not sold there.

contained on it; "In the additional equipment section, you have interpreted the heater as HD Heater = heater delete. I believe the 'D' is actually an 'O' meaning a HO heater, or a 'Deluxe Heater' with a list price of \$16.75. You also mention the car was 'sold in Min-

I think the order for

Other car packing slips from this period list the zone location where the dealer is located geographically in the upper left corner of the form, and the lo-



cation of the dealer town that ordered the car immediately below it. On the Packing Slip in the upper left corner, it shows 'MPLS.' on the top line

and 'Zone' below it. In the special equipment section are the words 'Tag Red Lake Falls.' 1 think this Packing Slip represented a car that was ordered as a zone company car for shipment to the dealer in Red Lake Falls (a small town in northwestern Minnesota). It was probably a car ordered for a Buick field man to be shipped to Red Lake Falls for pickup."

One of our newest members Marvin Krug (#1529) in Elizabeth, IL is restoring a '37 Special Sedan Model 41 that his

uncle bought new. He purchased it from his uncle around 1951 and drove it until 1959. Now he is restoring it. The motor and transmission have been rebuilt, the body is off the frame and he is removing the old brake lines before sandblasting and painting the chasis. He heard about the club from our member Ralph Ramsby (#212) in Rockford,

Marvin. Hope it helps you with your restoration.

From 1925 to 1978, this miniature steam train carried children around the San Francisco Zoo until being mothballed to make way for a gorilla exhibit. Then for many years it was stored inside the elephant house where winter rains would drip through the leaky roof onto the train.

Last year, zoo offi-

cials decided the all-but-forgotten train was now a beloved heirloom. One of our long time members, Don Micheletti (#250), the engineer in these

> two photos, and other members of the Golden Gate Railroad Museum spent 10 months working on the restoration including converting the boiler to natural gas and repairing the three wooden passenger cars.


> This old relic of a ride is again delighting children and their parents at the San Francisco Zoo.

> At the top of page 7 we see Roddy and Angie of the Brooklyn Car Club giving a demonstration of how to do the Swing. That's Anthony Wright's (#1192) '37 Century Se-

dan Model 61 in the background.

The photo in the middle of page 6 shows Donald Douglas, President of Douglas Aircraft Company in front of his '38 Buick convertible and a Douglas DC-3 airliner with United Air Lines markings.








This last photo shows a 1938 Special (Special's had the ivory steering wheel, Century's were mahogany colored) wreck appeared in the August 24th issue of Old Cars Weekly. It was sent in by Liegh Hopper of Montvale, New Jersey. Note the single instead of the normal dual driving light. I doubt this car is still on the road.

Ronn Pittman (#1188) in Batavia, Illinois is a certified associate IAAA appraiser. He can appraise autos, trucks and toys and will give a discount to club members. If you're interested, you can contact Ronn at (630) 879-7393 or his cell phone: (630) 202-1956.

The 1937-1938 Buick Eastern Club Meet will be held June 6-8, 2001 in Gananoque, Ontario, Canada. This is on the Canadian side of the St. Lawrence river. The Provincial Inn Motel in Gananoque will be our base as we explore some natural wonders, some Canadian countryside and a little bit of history. We will visit Kingston and tour Old Fort Henry, then move inland to a small artisan village to explore and shop. Finally we'll cruise the 1000 islands with a stop at a turn-of-the-century castle. Our hosts will be Bob and Doreen Ward (#114). More details in the next Torque Tube.













The front and rear covers show an unusual 1938 Buick Special motor home with one side mount (on the right hand side) and a sealed beam headlight conversion. It's owned by **Jim Hudson** (#1275) in Minnesota. See story below.

### My Buick Motor Home

By Jim Hudson (#1275)-Mendota Heights, MN



This photo shows me with my1938 Special motor home. I purchased it in 1996 from Steve Whitehead in Pocatello, Idaho. The unverified story that came with it was that it was made from a Buick sedan by C. W. Kepwood. Mr. Kepwood was an associate of Wally Byam who founded The Airstream Trailer Company in the 1930's.




Legend has it that Wally Byam created his classic aluminum travel trailer because his wife refused to go camping without her kitchen. Into his rounded, factory-made shells he built many of the comforts of a 1930's home. And so did Mr. Kepwood.






My motor home also appears to be of 1930's vintage with a rounded body shell. There is a hinged lid below the rear window that opens to a storage area. The aluminum skin was attached to a wooden frame. You can see the storage area below the rear window. The letters BUICK are on the rear bumper.

On the body is this faded decal that reads UMC with MOTOR on the top of the oval and CLUB below. I believe the "U" stands for United. Does any member know anything about the United Motor Club?



It has a push-button starter mounted next to the throttle with a later model steering wheel and steering column with turn signals. It still has the standard manual floor transmission.



It has a brown painted dashboard with factory blanking plates instead of the clock and radio.

It also has a double bed and plenty of drawers for storage. A '38 dome light is over the bed. Supposedly Mr. C. W. Kepwood, the builder of the motor home, suffered a stroke and died in it. Mr. Kepwood had relatives in Shoshone, Idaho and the motor home ended up there on one of his relative's farm. The motor home was stored with wooden pallets all around it, forming a wall. Then a sheet metal roof was installed on top of the pallets.

This was the scene when Steve Whitehead discovered it in 1972. Steve bought it and used it for camping. It caused quite a commotion when he drove in the camp grounds. Then Steve stored it in his barn in Pocatello, Idaho until he sold it to me in 1996. It is now under restoration. The Vintage Airstream Club and a Motor Home Museum in Elkhart, Indiana are now helping me research my motor home. If anyone in the 37/38 Buick Club has anymore information on this motor home or the United Motor Club, please call me toll-free at 1-800-247-1368. Thanks.



# MYDECAR



My car in front of the Montana State Capital

My Buick is a 1938 Special 2 door trunk-back sedan Model 48. The story behind it is that about 20 years ago my father and my sister were driving by an old farmhouse in Sun River, Montana. My father mentioned that his father (my grandfather) had owned a Buick like that one. Well, all the kids contributed enough money to buy the car for my father's birthday. That would have been in 1979 or so.

We approached that owner, Emma Toman. It was her husband's Buick and he had passed away. She agreed to sell it to us, and we gave it to my father. I have kept in touch with Mrs. Toman and have mailed her pictures of the car. I am an old

By Tom McGree (#1490) - Helena, MT

car buff and on my 50th Birthday last October my father gave me the Buick.


Since 1979 it has been repainted black and has been re-upholstered and cleaned-up. I have had lots of fun fixing little things like new windshield wipers, brake and clutch pedal pads and the map light. I have replaced the front end, tie rod ends, bushings, etc. It runs well. I replaced the differential gasket because it leaked a lot. Now it is little things like one ashtray is missing etc. I think someday I would like to replace the clutch and maybe put in new rings etc. but that will come with time. It has been a lot of fun for me and my family.






# FIAID'S NIGHT OUT!


By Gary Glazier (#1005)-La Crescenta, CA




This 1938 movie stars Ben Holmes, Joan Fontaine, Hedda Hopper and a 1938 Special Convertible Coupe. Fontaine is a heiress who is mistaken for a maid in this low-budget comedy. The film opens with the '38 rounding a turn and heading straight for a fish vendor trying to cross the street with his push-cart.



The car has just smashed the cart. Notice the ivory steering wheel indicating it's a Special. ('38 Centurys had a mahogany wheel). Even though it's a new car, it does not have the two front bumper guards and center bumper badge.



The driver gets out to check the damage.



He points to the smashed grille as the crowd looks on.



The driver gets back in the car and starts arguing with the fish vendor. Note the dead fish on the hood.



The driver and his passenger (Joan Fontaine) talk to a man off-camera in this shot. Note the windwing and side view mirror have been removed, probably to get an unobstructed view of the driver.



The driver and his girl friend drive away. Notice the black top boot (indicating a black top). Buick offered tops in either black, tan or blue-grey. Again the absence of the two bumper guards.

For some reason, all four bumper guards were removed.

# We were looking for a Buick and found one advertised in Hammings in March, 1997. The

We were looking for a Buick and found one advertised in Hemmings in March, 1997. The car was in Jacksonville, Florida. After we contacted the owner, he forwarded a video of the car. We looked at the video and decided to forge ahead and see the actual car. We test drove the car and all seemed well, so we purchased it and the next day started on our way home to Alabama.

As we drove home, it did not take long to notice that the car was overheating. We learned it had a bad water pump that was leaking. We had to stop every 10 miles or so and replace the coolant! It took us two full days to drive 400 miles!

Our car is a McLaughlin Buick built in Canada. We researched the car and found that only 5,081 Buicks were built in Oshawa, Ontario in 1938. (Compared to 79,000 in Flint). Most were exported, but we have found that only 8 of the type we have, #4419 (Model 41) without side-

By Robert Reed (#1183) - Alabama

mounts, are left. We have the original shop and owner's manuals. The car is different from the US built models in that the wheels and brakes etc. are all Chevrolet truck. There are other differences such as the hub caps and the optional oak wood grain dash and window frames.

After we bought the car, we replaced the radiator and water pump and began enjoying it. In January, 1999, we sent the car to Jenkins Restorations in North Wilkesboro, NC. They only do Buicks and Cadillacs.

The car returned home in June, 1999. It's in perfect running condition. We have since driven it on several trips. We use the car every Sunday to go to church. We bought and restored the car to drive and enjoy!



### 1937-1938 BUICK Technical SPECIFICATIONS

From MoToR's Auto Repair Manual - 1943 Edition



				E	NGI	NE D	ATA	
	YEAR AND MODEL	SERIAL NO.	ENGINE NO.	BORE AND STROKE	Piston Displacement, Cubic Inches	Compression Ratio, Std.	Taxable H.P.	BRAKE H.P. G R.P.M.
1937	Eight37-40	2999497 to 3219847	4-3166225 to 4-3396936	33/32 x 41/8	248.0	5.70	30.63	100 @ 3200
	Eight37-60	2999497 to 3219847	6-3176225 to 6-3396936	37/16 x 45/16	320.2	5.75	37.81	130 @ 3400
	Eight37-80	2999497 to 3219847	8-3176225 to 8-3396936	37/16 x 45/16	320.2	5.75	37.81	130 @ 3400
	Eight37-90	2999497 to 3219847	9-3176225 to 9-3396936	37/16 x 45/16	320.2	5.75	37.81	130 @ 3400
1938	Eight38-40	(F)1-3219848 to	4-3396937 to 4-3572651	33/32 x 41/s	248.0	6.15	30.63	107 @ 3400
	Eight38-60	1-3388546 or (L)3-3245765 to	6-3396937 to 6-3544292	37/16 x 45/16	320.2	6.35	37.81	141 @ 3600
	Eight38-80	3-3376382 or (C)2-3238767	8-3396937 to 8-3544292	37/16 x 45/16	320.2	6.35	37.81	141 @ 3600
	Eight38-90	to 2-3386843	9-3396937 to 9-3544292	37/16 x 45/16	320.2	6.35	37.81	141 @ 3600

SERIAL NUMBER LOCATION— 1935-1937: On the frame under right front fender.
1938-1940: On the right frame side rail under the hood.
ENGINE NUMBER LOCATION—1936-1942: series 40 and 50: on right side of engine near front.
1936-1942: series 60, 70, 80 and 90: on right side of engine near rear.
(F) Flint production. (L) Linden production. (C) California production.

#### TUNE UP CHART

FIRING ORDER-1-6-2-5-8-3-7-4.

NEGATIVE battery terminal grounded. BTDC-Before Top Dead Center

	SPARK PLUG		BREAKER		ú	SPARK ADVANCE CHRANKSHAFT DEGREE @ R.P.M.		dvance,			TAPPET	
YEAR AND MODEL	Make and Number	Gap,	Gap,	Spring Pressure, ounces	Cam Angle. Degrees	Start	Mazimum	Maximum Vacuum Ad Crankshaft	Location Timing Marks	Spark Timing, Degrees	For Running, Hot	For Timing, Intake
1937, 37-40	AC-H9	.022-	.0125-	17-21	31	2 @ 500	26@3300	11	Flywheel	2 BTDC	Int015 Ex015	.015
37-60 37-80,90	AC-H9	.022-	.0125- .0175	17-21	31	2 @ 500	16@1650	11	Flywheel	10 BTDC	Int015 Ex015	.015
1938, 38-40	AC-46	.023-	.0125-	17-21	31	3.5 @ 500	26@3000	11	Flywheel	4 BTDC	Int015	.015
38-60 38-80,90	AC-46	,023- .028	.0125- .0175	17-21	31	3.5 @ 500	26@3000	11	Flywheel	6 BTDC	Int015 Ex015	.015

#### VALVE MEASUREMENTS AND COMPRESSION PRESSURE

YEAR		STEM		TAPPET CLEARANCE			SPRING PR		VALVE SEAT	COM- PRESSION
AND			Runni	ng, Hot	Tin	ning	Valve	Yalve	ANGLE,	PRESSURE
MODEL	Intake	Exhaust	Intake	Exhaust	Intake	Exhaust	Closed	Open	DEGREES	AT R.P.M.
1937, 40	.0015- .0035	.0021-	.015	.015	.015	.015	1 151/2-201/2@121/22 O 261/2-311/2@115/16 C 42-52 @115/16	1 45-51@15/16 O 67-73@119/32 C 112-124@115/32	45	120@1000
60 80 90	.0015-	.0021-	.015	.015	.015	.015	1 151/2-201/2@121/12 O 261/2-311/2@115/16 C 42-52 @115/16	1 45-51@15/16 O 67-73@119/32 C 112-124@115/32	45	119@1000
1938, 40	.0015-	.0021-	.015	.015	.015	.015	1 151/2-201/2@121/32 O 261/2-311/2@115/16 C 42-52 @115/16	1 45-51@15/16 O 67-73@119/12 C 112-124@119/12	45	126@1000
60 80 90	.0015-	.0021-	.015	.015	.015	.015	1 15/h-20/h@12/hz O 26/h-31/h@15/is C 42-52 @115/is	1 45-51@15/16 O 67-73@119/32 C 112-124@119/32	45	130@1000

I-Inner spring

O-Outer spring

C-Combined pressure of both springs.

#### **ENGINE CLEARANCES**

YEAR	PIST	PISTON		RING CAP		ROD BEARINGS		MAIN BEARINGS		
AND MODEL	Тор	Bottom	Oil	Comp.	① Clearance	Clearance	Endplay	Thrust on No.	Endplay	Clearance
1937, 40	.0185- .0255	.0015-	.010015	.010015	.00030004	.00080018	.005010	3	.004-007	.0007-0022
60, 80, 90	.0215- .0285	.0015-	.010015	.010015	.00030004	.00080018	.005010	3	.004-007	.0007-0022
1938, 40	.018025	.0015-	.010015	.010015	.00030004	.00080018	.005010	3	.004-007	.0007-0022
60, 80, 90	.021028	.0015-	.010015	.010015	.00030004	.00080018	.005010	3	.004-007	.0007-0022

#### MAIN AND ROD BEARING JOURNAL DIMENSIONS

YEAR		DIAMETER AND LENGTH, INCHES										
MODEL	No. 1	No. 2	No. 3	No. 4	No. 5	No. 6	No. 7	Rod Bearings				
1937, 37-40	25/16 x 117/64	23/8 x 15/16	27/16 x 15/8	21/2 x 15/16	29/16 x 21/32	None	None	2 x 17/32				
37-60, 80, 90	29/16 x 19/32	25/8 x31/32	211/16 x 115/32	23/4 x 31/32	213/16 x 215/32	None	None	21/4 x 15/16				
1938, 38-40	25/16 x 117/64	23/8 x 15/16	27/16 x 15/8	21/2 x 15/16	29/16 x 21/12	None	None	2 x 11/4				
38-60, 80, 90	29/16 x 19/32	25/8 x31/32	211/16 x 115/32	23/4 x 31/32	213/16 x 215/32	None	None	21/4 x 15/16				

#### FRONT END MEASUREMENTS

YEAR AND MODEL	CASTER, DEGREE	CAMBER, DEGREE	TOE-IN, INCHES	TOE-OUT ON, TURNS, DEGREES	KINGPIN INCLINATION, DEGREES	KINGPIN DIAMETER, INCHES
1937, 40, 60	1/4 土 3/8	-1/4 to +1	0 to 1/16	231/4 ± 3/4	31/2 to 41/2	.861 — .862
80	0 ± 3/8	-1/4 to +1	0 to 1/16	233/4 ± 3/4	41/4 to 51/4	1.061 -1.06255
90	0 ± 1/8	-1/4 to + 1	0 to 1/16	24 ± 3/4	4 to 5	1.0615 -1.0625
1938, 40, 60	一7/8 土3/8	-1/4 to +1	0 to 1/16	231/4 ± 1/a	31/2 to 41/2	.861 — .862
80	一7/8 ± 3/8	-1/4 to +1	0 to 1/16	233/4 ± 3/4	41/4 to 51/4	1.0615 -1.0625
90	-7/8 ± 3/8	-1/4 to +1	0 to 1/16	24 ± 3/4	4 to 5	1.0615 -1.0625

© With outer wheel turned to an angle of 20° degrees, inner wheel sould set as specified.

#### LUBRICATION AND CAPACITY CHART

		ENGINE			TRANSMISSION	V	REAR	AXLE		
YEAR AND MODEL		S.A.E. NO.	REFILL, QUARTS	COOLING SYSTEM, QUARTS	S.A.E. NO.	TRANSMISSION CAPACITY, POUNDS	TRANS. & OVERDRIVE CAPACITY, POUNDS	S.A.E. NO.	CAPACITY, POUNDS	FUEL TANK, GALS.
1937,	40	S. 30	6	13 1/4	S. 160	13/4	NONE	S. 160EP	3	18
		W. 20W			W. 90			W. 90EP		
	60	5. 30	8	17	S. 160	21/2	NONE	S. 160EP	3	18
		W. 20W			W. 90			W. 90EP		20
	80, 90	S. 30	8	17	S. 160	21/2	NONE	S. 160EP	4	20
		W. 20W			W. 90			W. 90EP		
1938,	40	20W	6	13 1/4	S. 160	13/4/25	NONE	90HY	3	18
					W. 90					20
	60	20W	8	17	S. 160	21/2	NONE	90HY	3	18
					W. 90					10
	80, 90	20W	8	17	S. 160	21/2	NONE	90HY	4	20
					W. 90			20111	-	e.U

S — Summer. W— Winter. EP — Extreme pressure HY — Hypoid.  $\otimes$  — For semi-automatic transmissions, use 31/2 quarts of same oil used in engine.

#### **TORQUE WRENCH READINGS**

		POUNDS
WHERE USED	SIZE	FEET
0il pan drain plug		30-35
Lower crankcase	5/16	10-15
Flywheel to crankshaft	. 27 44	45-55
Wristpin clamp bolt	5/16	25-30
Main bearing bolt	37.20	120-130
Rocker arm bracket cap screw	3/8	30-35
Timing chain cover.	3/8	15-20
water pump to cylinder	3/8	25-30
Connecting rod, Series 40 and 50	7/16	45-50
Connecting rod, Series 60, 70, 80 90	7/16	60-65
Cylinder head bolt	7/16	65-70
Spark plugs	14 M/M	22-28
Spark plugs	10 34/34	7-10
Vibration damper retaining bolt		100-110
battery ground strap to crankcase		15-20
Manifold studs	3/8	25-30
Transmission support	3/8	20-25
Rear axle cover	3/8	10-15
Differential carrier to rear axle housing	3/8	20-25
Backing plate to rear axle housing	7/16	35-40
Spring scal to rear axie strut rod	1/2	65-70
Spring seat to rear axle strut rod	3/8	40-45
Strut rod to strut rod bracket	1/2	65-70
Torque tube to differential carrier	7/16	50-60
Shock absorber to rear axle brake backing plate	9/16	65-70
Shock absorber—rear	9/16	45-50
Shock absorber ninch holt	2/0	
Shock absorber to frame—front	1/2	25-30 60-65
Lower control arm shaft	7/16	
Pitman arm nut	77.10	45-50
Front brake backing plate to steering knuckle	7/16	70-75
Steering knuckle support pinch bolt	3/8	45-50
RUDDER Dumper to spring seat—front suspension	2/8	35-40
Steering connecting link clamp holt.	3/8	5-10
Steering gear to frame bolt.		35-45
Brake anchor nut-front and rear brake		55-60
Brake wheel cylinder to backing plate	5/16	80-90
Brake drum to rear axle shaft	5/16	15-20
Wheel bolts	1/2	15-20
Body bolts	7/16 0/17	60-65
	//10-9/16	25-30



By Harry Logan (#651)-Los Altos, CA

Many cars that lasted through World War II were pretty tired at the War's end. In an effort to keep Buick owners in their Buicks rather than switching to other makes, Buick offered new factory replacement engines. These are described in this ad from The Buick Magazine of February, 1947. (page 19)

The replacement engine program offered engines that would fit any 1937 to 1948 Buick. Both the small and big series engines were available and Buick dealers advertised that a complete new engine could be installed in twelve working hours.

This big series replacement engine has the number RE-504490 stamped into the block with the original engine number still on the number pad. The two numbers are totally different.

Some books say the replacement engines were shipped without numbers, but with the prefix "RE" stamped into the engine pad. The installing dealer would then punch the original engine's number after the "RE". That was not the case with this engine as the RE number was stamped into the block.

As design changes and improvements were incorporated in production engines, such as oil fil-

# PLACEMENT


ters, aluminum pistons and precision bearings, the replacement engines included these parts. Later replacement engines had hydraulic instead of mechanical valve lifters. The oil filter on hydraulic lifter engines was a low-restriction type designed especially for use with hydraulic valve lifters.

Depending on the year of the original engine. certain parts (such as the starter, generator, fan, fan belt etc) were to be removed from it and transferred to the new engine to serve in place of those parts which were not supplied with the replacement engine.

A throttle adapter was installed on Stromberg carburetors with three holes in it for connecting to the throttle rod. One hole was for 1937 only, the second for 1938 only and the third hole for

1939 through 1947 carburetors.


Buick provided dealers with Replacement Engine Installation Instructions. There were separate instructions for 1937, 1938, 1939, 1940 and 1942 through 1948 (except 1948 Dynaflow). The next two pages show the 1937 and 1938 Big Series Installation Instructions. Thanks to Bob James (#371) in Canada for sharing this information.



The best engine in the world can't last forever . . . even a sturdy, dependable Buick engine. But if you own a '37. '38. '39, '40. '41, or 42 Buick and the engine is mileage-weary from long, faithful service, you can now replace it with a brand new, factory-built engine.

This Buick "Power Package" will give your Buick a new start in life ... new pep and power that will make it lively as a young colt. The engine unit is complete with all necessary parts, and can be installed easily in one operation.

If the engine in your Buick is due for a major overhaul, ask your Authorized Buick Dealer about the "Power Package." The cost is less than you would think, and decidedly more economical than part-by-part replacement.





#### 1937 SERIES 60, 80 AND 90

In order to install the replacement engine in 1937 Series 60, 80 and 90 cars, the following removal, transfer and addition of parts will have to be made:

1. Remove the lower and upper flywheel housings and the flywheel from the replacement engine.

2. Install the flywheel and the upper flywheel housing from the 1937 engine. This housing must be realigned. See "Flywheel Housing Alignment" in the Shop Manual.

3. Remove the front support plate from the replacement engine and install in its place the front support plate from the 1937 engine. Reinstall the following replacement engine parts: timing chain sprockets, timing chain, timing chain cover and seal, and the harmonic balancer.

4. Install on the replacement engine the following parts from the 1937 engine:

- (a) The clutch driven disc. The 1937 disc must be used because the splines of the disc are different from those of the present disc. The clutch pressure plate and cover from the new engine can be used.
- (b) The clutch release bearing, release bearing support, release bearing retainer, snap ring, paper gasket, clutch yoke and boot. If any of these parts are worn or otherwise defective, they should be replaced by new 1937 service parts.

(c) Timing hole cover.

(d) Lower flywheel housing and gasket. (e) Pressure gauge fitting in crankcase.(f) Battery ground strap.

(g) Starting motor.

(h) Cylinder water outlet. (i) Heater hose connections.

Radiator hose connections.

(k) Pulley, fan driven. It will be necessary to enlarge the hole in the pulley from 1/2 inch to 1/2 inch to accompdate the water pump shaft on the replacement engine.

(1) Fan and mounting bolts. It will be necessary to enlarge the hole in the fan from 1/4 inch to 5/8 inch to accomodate the water pump shaft on the replacement engine.

(m) Exhaust pipes. In order to bolt the exhaust pipe into place, it will be necessary to bend the pipe slightly. To effect a tighter joint at the heat trap the following parts should be used in conjunction with the 1937 exhaust pipe:

_	Group	Part No.
(1) Extension, exhaust pipe		1325413
(2) Gasket, exhaust pipe	3.611	1301200
Both of these parts are supplied in the replacement engine package. The		
Part #1325413, should be removed from the exhaust pipe furnished in		
in the 1937 exhaust pipe. The gasket, Part #1301200, should then be		
the exhaust pipe will not bolt up to the heat trap properly, the bolts ca	n be started	. If heat from
a torch is then applied to the bend nearest the heat trap the bolts can	be drawn up	securely, and
the pipe will be correctly bent.		

(n) Ignition coil. Install the 1937 ignition coil on the coil mounting bracket which is welded to the push rod cover of the replacement engine.

5. The fuel pump on the replacement engine has a vacuum booster. To connect this unit to the windshield wiper line an extension rubber hose may be used.

6. In order to use the 1937 throttle control linkage with the replacement engine it will be necessary to use the throttle adapter supplied in the replacement engine package. Install the adapter as shown in Figure 1 or 2, depending on make of carburetor.

7. The 1937 throttle operating rod is too short for this installation even after the aforementioned bracket has been made. This rod can be lengthened the required amount by using in conjunction with it the following parts:

Calcar Maria Cara Cara Cara Cara Cara Cara Cara	Group	LOL 140'
(a) Assembly, Ball Joint		1330891
(b) Lock Nut		122166
The trunnion by which the bottom of the throttle rod is attached to the acco	lerator peda	l level, should
be removed and Part #1330891 installed in its place. The throttle rod she		
the ball joint assembly, adjusted to the required length and locked there h	w means of l	Part #122166.

Group . Part No. (a) Pipe, crankcase ventilator outlet 1.762 1303514 (b) Belt, fan 1.416 1319975 (c) Generator .. U.M.S. 62U (d) Control unit, generator U.M.S. 1118201 (c) Bracket, generator mounting ..... 2.277 1325325 (f) Brace, generator ..... 2.317 1313946

It will be necessary to locate the generator brace in a new position. A 25/64" diameter hole, located as shown in Figures 3 and 4, should be drilled in the engine's front support. Shirns totalling 1/2" in thickness should be used between the brace and the front support plate.

9. Fill the sir cleaner reservoir with one pint of SAE-50 engine oil.

8. Install the following parts to complete the replacement engine assembly:

#### 1938 SERIES 60, 80 AND 90

In order to install the replacement engine in 1938 Series 60, 80 and 90 cars, the following removal, transfer and addition of parts will have to be made:

- 1. Remove the lower and upper flywheel housings and the flywheel from the replacement engine.
- Install the flywheel and the upper flywheel housing from the 1938 engine. This housing must be realigned. See "Flywheel Housing Alignment" in the Shop Manual. After the housing has been aligned, the clutch driven disc, pressure plate and cover from the new engine can be installed.
- Remove the front support plate from the replacement engine and install in its place the front support plate from the 1938 engine. Reinstall the following replacement engine parts: timing chain sprockets, timing chain, timing chain cover and seal, and the harmonic balancer.
- 4. Install on the replacement engine the following parts from the 1938 engine:
  - (a) The clutch release bearing, release bearing support, release bearing retainer, snap ring, paper gasket, clutch yoke and boot. If any of these parts are worn or otherwise defective, they should be replaced by new 1938 service parts.
  - (b) Lower flywheel housing and gasket.
  - (c) Pressure gauge fitting in erankcase.
  - (d) Battery ground strap.
  - (e) Starting motor.
  - (f) Generator.
  - (g) Generator brace and bracket.
  - (h) Cylinder water outlet.
  - (i) Heater hose connections.
  - (j) Radiator hose connections.
  - (k) Ventilator outlet pipe.
  - (1) Fan belt.
  - (m) Pulley, fan driven. It will be necessary to enlarge the hole in the pulley from ½ inch to 5% inch to accommodate the water pump shaft on the replacement engine.
  - (n) Fan and mounting bolts. It will be necessary to enlarge the hole in the fan from ½ inch to ½ inch to accommodate the water pump shaft on the replacement engine.
  - (o) Exhaust pipes. In order to bolt the exhaust pipe into place it will be necessary to bend the pipe slightly. To effect a tighter joint at the heat trap the following parts should be used in conjunction with the 1938 exhaust pipe:

Both of these parts are supplied in the replacement engine package. The exhaust pipe extension, Part #1325413, should be removed from the exhaust pipe furnished in the package and inserted in the 1938 exhaust pipe. The gasket, Part #1301200, should then be put in place. Although the exhaust pipe will not bolt up to the heat trap properly, the bolts can be started. If heat from a torch is then applied to the bend nearest the heat trap the bolts can be drawn up securely, and the pipe will be correctly bent.

- (p) Ignition coil. Install the 1938 ignition coil on the coil mounting bracket which is welded to the push rod cover of the replacement engine.
- The fuel pump on the replacement engine has a vacuum booster. To connect this unit to the windshield wiper line an extension rubber hose may be used.
- In order to use the 1938 throttle control linkage with the replacement engine it will be necessary to use the throttle adapter supplied in the replacement engine package. Install the adapter as shown in Figure 1 or 2, depending on make of carburetor.
- 7. If it is desired to use the hand throttle with the new engine assembly it will be necessary to install the following parts:


	Stromberg Carburetor	Group	Part No.
	(a) Assembly, hand throttle wire bracket	3.519	1320408
	(b) Assembly, hand throttle carburetor lever	3.482	1320417
	Carter Carburetor		
	(a) Assembly, hand throttle wire bracket	3.519	1320695
	(b) Assembly, hand throttle carburetor lever	3.482	1320694
_			

8. Fill the air cleaner reservoir with one pint of SAE-50 engine oil.




## OPEN CAR WINDSHIELD MOLDING COVER

By Harry Logan (#651)-Los Altos, CA



1937 and 1938 Buick convertible coupes and sedans had chrome plated window molding instead of woodgraining as on closed cars. The rear view mirror housing was also chrome plated and off-set 3 ½" (8.9 cm) to the right so as not to interfer with the center top hold-down latch. This left the center joint of the window molding exposed. In closed cars, this joint was covered-up by the base of the rear view mirror.




That's why Buick installed this small chromed cover to hide where the molding joined. The cover was held in place with a chrome self-taping screw. Thanks to *David Bylsma* (#117) in Maryland for suggesting this tip.


### BELT MOLDING Technical CLIPS

By Harry Logan (#651)-Los Altos, CA





One of our members was having difficulty installing the short piece of belt molding between the hood and door. He was using a clip with a screw and nut to hold it in place. This requires access to the area behind the clip which is often difficult to reach.



A better way would be to use push-on clips. A variety are show here. Use ones 3/4 " (2 cm) wide. And don't forget Buick used a molding clip with threads and a nut at the pointed end of the belt molding. So don't try to snap this clip out of it's body hole until you've first undone the nut from inside the trunk. Also note in the first photo that the thinnest edge of the 1938 molding goes on top. Thanks to **John Jackson** (#1107) in Peoria, IL for suggesting this article.

Marvin Krug(#1529) Box 60, 218 Catlin St. Elizabeth, IL 61028 37-41

Dennis Bachmann (#1530) 1545 Wilshire Blvd. Suite 700 Los Angeles, CA 90017 38-46 38-61

Michael Doyle (#1531) Box 11, Site 7, RR 3 Olds, Canada T4H 1P4 38-41

Allan Rucka (#1532) 850 S. Collier Blvd Apt. #1402 Marco Island, FL 34145

John Pollock (#1533) PO Box 265 Batesville, VA 22924 37-61

Ron Trull (#1534) 4746 Rainbow Dr. Kannapolis, NC 28081 37-46

Henry Kowalski (#1535) 6542 Sauk Trail Rd. Cedar Grove, WI 53013 38-41

James Grogis (#1536) 4211 State Rd. M-28 Autrain, MI 49806

Howard Crawford (#1537) 2165 Wide Oak Ct. Chesterfield, MO 63017

Mary Beagin (#1538) 14820 Bledsoe St. Sylmar, CA 91342 37-41

#### Back Issues Still Available

The following BACK ISSUES are available for \$4.00 each Postpaid.

- 1991-1992 Volume X Numbers 1, 2, 3, 4, 5, 6, 7, 8 & 9
  - 1992-1993 Volume XI Numbers 6
  - 1993-1994 Volume XII Numbers 2 and 6
    - 1994-1995 Volume XIII Number 6
  - 1995-1996 Volume XIV Numbers 3 through 6
    - 1996-1997 Volume XV Number 5 & 6
  - · 1997-1998 Volume XVI Numbers 1 through 6
  - 1998-1999 Volume XVII Numbers 1 through 6 Please make your checks payable to:

The 1937-1938 Buick Club, 1005 Rilma Lane, Los Altos, CA 94022 USA 

#### BIG SERIES ENGINE FOR SALE

Buick straight 8 engine and transmission with insert connecting rods. These rods can be used on 37/38 Buicks to convert them to insert bearings. Believed to be a '52 or '53 Big Series engine. Engine complete with generator, starter, distributor, carburetor etc. It was removed from a car being made into a street rod. It is in my way, but I don't want to see it scrapped. 

Tom Miller

Boonville, CA

(The nearest city of any size is Ukiah, about 20 Miles away. I am 125 miles N. of San Francisco, off of Highway 101).

Phone: (707) 895-3405 E-mail: tom@pacific.net

### Parts FOR SALE

- 1037/1030 DADTS		
• 1937/1938 PARTS Upper outer pins	80-90 series	\$55
Lower outer pins	40-60 series	
King pin set	80-90 series	
Tie rod ends	60 series	
Master cylinder	60 series	
Master cylinder	80-90 series	
Brake shoes	60-90 series	
Timing chain	60-90 series	
Cam gear	60-90 series	
Crank gear	60-90 series	
Cam bearings	60-90 series	
Exhaust valves	60-90 series	
Intake valves	60-90 series	
and address to be an in the second	ual	
	ual	
Carl Dahl (#86		
2217 9th Aven		
Sacramento, C		
Phone: (916) 4		
	series, NOS	
	***************************************	
	ing hardware	
	os	
	NOS	
	0 series for coupe & convertible coupe 8 piec	
1938 PARTS	The second secon	4230
Oil gauge, NOS		\$75
Temperature gaug	e with sending unit and gas gauge	\$95
Rocker molding, N	NOS, 60 series	\$250 pair
1937/1938 PARTS		par.
Horn ring, chrome	d	\$125
Door handle w/loo	k and key, exterior	\$95
Headlight lens, NO	OS, left & right	\$75 each
For complete parts list f	or '37 & '38, e-mail FAX number or mailing addres	ss to BUICKPTS@AOL COM
Bell Buick Pari	S	zerom isonot.com
124 E. Colby S		
Whitehall, MI		
Phone: (231) 8	94-5301 FAX: (231) 894-9851	

• 1937/1938 PARTS
Parting 1937 and 1938 Buicks. The following is just a portion of what's available. Call with your needs.

• 1937 PARTS	and their four trees.
Special fuel pump, rebuilt by Arthur Gould	560
Grille, reproduction	
Century wheels., excellent condition	\$100 each
Parts radio	\$25
Coupe and Convertible coupe left taillight, complete	
40/60 Series rear brake cables, good condition	
Master and deluxe heaters	
Century radiator	
Special radiator	
Rear springs 40 & 60, good condition	
Radio delete plates	
Small series throttle linkage	
Big Series rocker assemblies	\$50
Fender lights	
Trunk lights, complete	
Tail lights with lenses, all series	
Wiper transmissions.	
Special manifold	
Throttle cable	
Special transmission	
Special splash pans	
Century hood	
Headlight switch	
Radio grilles	¢15
Wiper motors	
Trunk hold-up arms.	
Sun visors	
Bumpers	
Bumper arms	
Steering wheel	
40 & 60 running board brackets	
Buick creast badge for hood trim strip.	
Gas pedal Small and large series generators	
• 1938 PARTS	
Coupe trunk handle base, light and handle w/keyNOS	6175
Bumber badge	
Horseshoe grille guard	\$100
Special hood hinge	
Radio, complete with good face	\$100
NOS left taillight housing and base, no lens	5100
Century motor, complete long block	
Century hood tops and side panels	5500
Fender lights	
Limited door sills	5100 pair
Breather tubes	Set of four
Trunk hold-up arms	510 each
Trunk hold-up arms	
734Z starter with solenoid	500
Defroster ducts	520 pair
Denoster ducts	

W	Viper transmissions	\$50 pair
R	ear license plate stand, bracket & light for sedan	\$45
	ail lights, complete	
	ssist straps with screws	
	hrottle cable	
	pecial radiator	
	attery tray	
	pecial manifold, complete	
	pecial hood sides & tops	
	rille, no cracks, minor pitting	
	entury radiator	
	37/1938 PARTS	
L	arge series transmissions	\$300
	pecial sidemount covers, complete	
	pecial air cleaners	
	adio hanger brackets	
1:	arge series flywheel with good teath	\$100
	estored nose stainless	
	arge series sidemount cups	
	ig Series spark plug cover	
1.	leadlight buckets	
M	arge series fan belts, new	
	Iap light switches	
	mall series spark plug covers	
R	ear fender splash aprons	\$15 each
B	ig Series manifold ends	\$50
10	6" beauty rings	\$10 each
н	eadlight bezels	\$20 each
11	runk hinges	\$50 pair
Fi	ront arm rests	\$25 pair
40	0 & 60 rear vent windows, need plating	\$50 pair
R	ear view mirrors	
S	pecial rear motor mounts	\$15
	entury rear motor mounts	
4(	0 & 60 4 dr. sedan doors	\$75 each
Fi	ront vent window frames & mechanisms	\$35 each
Bi	ig Series fuel pump cores	\$50
4-	Post voltage regulator, used	\$25
13	5" Beauty rings	\$10 each
H	eadlight adjusting buckets	\$100 pair
Fi	ront license plate bracket	\$35
	Dave Tacheny (#997)	
	11949 Oregon Ave. N.	
	Champlin, MN 55316	
	(612) 427-3460	

#### • 1937 PARTS CAR

1937 4-door slant back sedan parts car. Has 1936 wheels.

No front fenders or cowl. Must pick up.

John McNerney (#1439)

RR 1, Box 772

Venus, PA 16364-9628

Phone: (814) 354-2459

### Parts WANTED

#### WANTED FOR 1938 CONVERTIBLE: |

- 1938 Convertible coupe rumble seat lower (bumper) step plate for 1930 to 1938 convertible and sport coupes.
- Right rear bumber mounting lug for above step plate. Fits all convertible and sport coupes 1930 to 1933 and 1936 to 1938.
- Lamp, rear license. Used on 1938 to 1941 40-80 series streamline phaetons, streamile 4-dr sedans, convertible coupes, business and sport coupes. The trunk handle fits through it. Must be in excellent or new condition.

D. Hugh Morris (#322) 11213 Forest Rain San Antonio, TX 78233 Phone: (210) 653-9688

#### WANTED FOR 37/38 CONVERT:

For a 37/38 convertible coupe. Bumper (*lower*) rumble seat step plate and attaching bracket.

Adolpho Martinez (#1460) San Diego, CA Phone: (619) 472-0799

#### WANTED FOR 1937:

Need 2 sidemount fenders and covers for a 1937 Special.

Jack Jackson (#1312) 120 Travois Rd. Louisville, KY 40207-1674 Phone: (502) 893-8241

### Gars FOR SALE

#### FOR SALE: 1937 SPECIAL

4-Door Fastback Sedan Model 47
Black, 88,000 original miles,
tan interior, wide whitewall tires,
fog lights. I am the second owner.
I have the original bill of sale and
maintenance records. Runs like new.
\$11,995.

Leslie Morrow PO Box 156, White Stone, VA 22578 Phone: (804) 436-0111





#### FOR SALE - 1937 CENTURY 60C:

1937 Century 4-Door Convertible Sedan Model 60C. Body-off restoration some years ago. A beautiful maroon car. 410 made, 11 exported. Has vinyl interior. Some minor paint chips.

\$32,500. obo.

Bob Ankenney (#1116) Box 208 La Mirada, CA 90637 Phone: (714) 449 0114

### More FOR SALE



#### FOR SALE: 1938 CENTURY

Blue 1938 Century Opera Coupe Older restoration in beautiful condition. \$22.000.

Jerry Helmuth 321 E. County Line Rd. Calimesa, CA 92320 (909) 795-1379

#### FOR SALE: TWO - 1937 Limiteds

- '37 Limited Sedan Model 90 Dual sidemounts. Two jump seats. \$10,500.
- '37 Limited Sedan Model 90 Parts Car

\$2,000.

Frank Cwikla (#1111) 1909 Goodin Rd. Friendship, WI 53934 Phone: (608) 339-6297

#### FOR SALE: 1937 SPECIAL

1937 Special 4-Door Trunk Back Sedan Model 41. Gray with taupe Hampton coach interior, wide whitewall tires, radio w/extra speaker, heater/defroster, driving lights and grille protector. All chrome and wood graining done.

\$13,500.

Jerry Root (#422) 71 South Pollard Drive Fulton, NY 13069 Phone: (315) 593-2346

#### FOR SALE:

#### 1937 Roadmaster & Century

 81F with division window. Dual sidemounts. 99% complete with newer wiring harness, title, needs restoration.

\$4,000. or offer.

 Century 4-Door sedan Model 61. Solid and straight. Runs and drive good.

84,500.

with sidemounts ..... \$6,000.

Dave Tacheny (#997) 11949 Oregon Ave. N. Champlin, MN 55316 (612) 427-3460

#### FOR SALE: 1937 CENTURY

1937 Century coupe. Modified. Chevy Nova front subframe, Camaro rearend & springs, Buick 3.8 V-6 engine, power steering, disc brakes, windows, & antenna. Bright white acrylic urethane paint, custom blue cloth & vinyl interior with wood trim on dash. Tinted glass, 4 speaker stereo system, cold air conditioning. New tires with less than 1000 miles & new battery. 21,000 dependable miles since completion. Asking

\$14,500. O.B.O.

I would rather trade this car for a '47 thru '49 Buick convertible or sedanette of same or less value. OR what kind of Buick convertible do you have? My kids need more room in the back seat so I need a different car!! Pictures on request.

Greg Marshall 252-635-9052 6 to 9 p.m. Eastern time

### Gars WANTED

#### WANTED: 1937 RAODMASTER

4-Door Trunk-Back Sedan Model 81 with sidemounts. Must be low mileage original or low mileage recent restoration in number 2 or better condition.

John Welby (#1497) 1665 Shipman Rd. Oxford, MI 48371

Phone: (248) 628-8787

#### 1938 BUICK SPECIALS BY VICTORY MODELS



CTORY

1/43 RD SCALE



#33 \$2.00

VISA

Master Card

VL-1 1938 BUICK SPECIAL SEDAN VL-2

Additional BODY STYLES coming including a TAXI – Also coming soon a 1940 Busck Super – SHIPPING \$6.00 first model, & \$1.00 each additional model Send Inquiries and Checks Payable to

RAY PASZKIEWICZ, JR.

P.O. BOX 156, CLARKSBURG, N.J. 08510 . TEL. 732-446-9381

FAX 732-446-09297

#### ONE OF A KIND CAR DISPLAY POSTERS!

Beautiful, Descriptive, Framed Collector Car

DISPLAY POSTERS

for Car Shows are my specialty,
These Hand Made Posters really add that
"SPECIAL TOUCH" when displayed next to your car.
Prices start at \$50.00 and up depending on
Color, Size and Rendering of your car.

Al Lovi (#994) ART DESIGN STUDIO 95 Brianne Circle, Windsor, CA 95492 (707) 837-1786

#### **CONVERTIBLE SUN VISORS**



\$195.00 each Plus 8% tax for California residence
These are authentic visors. All parts are chrome plated.

WALLACE WAMSLEY (619) 283-3063

4732 Bancroft Street #7, San Diego, California 92116

#### 1904-1965 BUICK RESEARCH SERVICE

More information and detail about your specific 1937 or 1938 Buick year, model and serial number than you can get from any other source. SATISFACTION GUARANTEED.

Complete Research Package \$50.00, \$60.00 if shipped outside the USA.

Additional information available upon request, or send year, model, serial number, engine number, car photo (if available) and Fisher Body data plate rubbing.

#### 1937 BUICK HIGH QUALITY VIDEO

1937 Buick video made from the only known copy of a 16 mm black & white sound film produced by Buick Motor Division in 1937. The tapes have been made by a professional video dubbing studio. They are very high quality and are produced from a digitally mastered original. Video runs approximately 32 minutes and contains a number of segments showing the construction of the 1937 Buick and Buick's place in American society. Historically significant item. SATISFACTION GUARANTEED. \$39.95 including shipping.



#### TERRY DUNHAM

AUTOMOTIVE RESEARCH SERVICES



P.O. Box 4057, Apopka, Florida 32704-4057 \* Phone 407-880-0797 e-mail: Buickohv@aol.com \* web site: www. OldBuickArchive.com

#### 1937-38 BUICK






Glue-in	DW-378	\$1.90 ft.
Clip-in	DW-80	\$3.50 ft.
Clips	WC-80	\$0.75 ea.











TRUNK SEAL For COUPES, 5/8" x 1" 



HOOD REST PADS, 1937-38 6-8 Per. Car.

DASH GLASS, SILK-SCREENED on Back of

Glass in Colors as Original.



CLUTCH and BRAKE PEDALS Ser. 40-60 Brown CR-343RN 56.25ea



RADIO......RG-37......\$28 ... CLOCK.......CG-37.......\$28 SPEEDO.... DG-38.... 1938... ....539 RADIO...... RG-38.. 528 CLOCK......CG-38.. 528

1937..... SPEEDO.... DG-37...



PEDAL FLOOR SEALS; All Models FS-375...... \$12.95 pr.



PLASTIC DASH KNOBS..... ....DK-37/8...... \$6,00 PLASTIC DOOR HANDLE and Window-



1937 ONLY! ACCELERATOR PEDAL Ser 40-60 Black......AP-37B...... \$32.00 ...AP-37BN.... . \$35.50



OUTSIDE DOOR HANDLE CHROME and RUBBER GROMMETS. I FERRULE & I GROMMET Per Set. 1937 ..... DGF-296... \$9.50/Set .. DGF-380.. \$5,50/Set 1938...



SHIFT BOOT. 1937-38 Series 40 Only! Black \$9.75 \$18.50 Brown. Series 80-90 Black Only... .58.50

DOOR SILLS; Trim To Fit






2-Door \$69.50 pr. 4-Door. \$104,25 set GLOVE BOXES .....



1938 TRUNK HANDLE/LIGHT MOUNTING SEAL......DH-381..... ... \$9,75

> ... \$11.00 pr. .... \$52.50 pr.

PARKING LIGHT LENS...



1937 HUB CAPS. All Ser ......... HC-37......


Wheel Beauty Rings 15"or16".....



529.25


CARB, KITS: CARTER CK-360C.... \$26.50 Stromberg CK-37XS... \$27.50





TORQUE BALL SEAL KIT. All Models TBK-343....

LF-333P....



...527.00 ea.

\_ \$62,00 Pair



SHIPPING (Unless otherwise noted on Invoice) Minimum Shipping Charge... \$17.50-\$49.00 Order..... \$50.00-\$99.99 Order... \$100 and up.... .. \$9.95

FRONT END PARTS For 40-60 Series; King Pin Sets .... . \$39.75 Lower Inner Bushings...... ....\$22.00 Tie Rod End.... ..\$27.00



BOB'S AUTOMOBILIA BOX 2119 ATASCADERO, CA 93423 TELEPHONE (805) 434-2963 VISA - MASTERCARD - DISCOVER or C.O.D. CATALOG #47 \$5.00 or ONLINE at www.bobsautomobilia.com

#### BUICK...Upholstery and Top Kits 1927/1955


Since 1977.. Hampton Coach has been producing only the finest quality Interior and Top products available for GM cars. We offer complete interior Kits, Seat Upholstery, Tops and related accessories as well as "era" fabrics by the yard. Inquire Toll Free

1-888-388-8726



www.hamptoncoach.com

6 Chestnut Street Tel 978-388-8047





Restoration and repairs that are correct and authentic. "I know your Buick."

Former Director of Long Island, NY Chapter now has fully equipped shop in North Georgia. Ron Stanger, BCA #21079

Classic Car Works Ltd., 3050 Upper Bethany Rd. Jasper, GA 30143 Phone (770) 735-3945



2533 W. Cypress St. Phoenix, Arizona 85009 (602) 278-4505

Beautifully Recast STEERING WHEELS Call or write for brochure



RESTORATION



SERVICES

Running Board / Rocker Moldings

SSAE for Information

**BUICK RESTORATION SERVICES** 

P.O. BOX 442, PERRY.

MICHIGAN

48872



#### 1927 thru 1953 WIRING HARNESSES

**AUTHENTIC REPRODUCTION** WIRING SYSTEMS THRU 1953 HAND CRAFTED WITH THE **FINEST MATERIALS** 

EACH SUPPLIED WITH:

- LIMITED WARRANTY
- INSTALLATION INSTRUCTIONS
  - SCHEMATICS

ALSO OFFERING:

WIRING SUPPLIES

CATALOG OR INFORMATION \$5



BOX 435 WAYNE, PA. 19087

